US ERA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared		3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill		11/26/2012		1230		
4. <u>Unit Name/Designators</u>		5. Unit Lo	5. Unit Leader		6. Operational Period :	
Containment Branch Recovery Team 1		Name:	Dan Capone START/US EPA		From:	11/26/2012 0730
		Position:	Operations Section Chief		To:	11/26/2012 1130
		7. Pe	ersonnel R	oster Assigned		
<u>Na</u>	<u>ime</u>		ICS Po	sition	DUTY (	CELL
Dan Capone		Operations	Operations Section Chief			
Rex Johnson		Containme	ent Branch	Director		
Sean Kane		Field Team Lead/CBR-4				
			Q A -4!-	.:4 T		
			8. Activ	ity Log		
					LAT	LAT
Activity Area	Morrow Lake	Morrow Lake (MP 37.50)			Various	Various
Tion in the second					(DD.MMMM)	(DD.MMMM)
	EXTENT OF	F OIL IMPA	CTED			
OIL OBSERVED	AREA DENSITY OF OIL /SHEEN					
<b>Total Collection</b>	DENSITY O	FOIL/SHE	EN			
Points						
Total Boom						
Deployed						
Activity	Oversight of Enbridge representatives (SWAT) attempting to remove hard boom anchor 'poles' (Clusters of three) within the main channel of Morrow Lake (MP 37.50). Only a portion of one anchor 'pole' was removed and that was due to the compromised integrity of the pole (pole snapped). An indeterminate length of pipe remains in the sediment. Assessment was determined that present equipment would not suffice for the removal of the anchor points and a specialized pontoon boat with mechanical winch would be mobilized to the site for morning operations on 11-28-12. Anchor cluster was re-wrapped with visible yellow hard boom and solar light placed on one of the remaining visible anchor points.					
Health and Safety Issues	None					
Comments	Boom Configuration F-1 and F-2 to be removed during the operational period of 11-21-12. Buoys, anchor points and containment sediment devices remain within the Morrow Lake Delta and are tentatively scheduled to be removed at a later date.					

		Detailed field notes with measurements are in CBR-4 Logbook.
--	--	--